

## Metals (2015)

Leon County's NPDES program requires trace element analysis monitoring for several stations throughout the County. Staff decided in 2012 to expand the trace element program to include all sampling locations to more accurately evaluate the County's wa-

tersheds. Trace elements naturally occur in very small amounts (few parts per million or less) in a given system. While a small amount of these elements are sometimes required for animal or plant life, many can be toxic at elevated levels (**Table 1**).

**TABLE 1. Trace elements sampled for by Leon County.**

Element	Anthropogenic Sources	Effects and Significance
Arsenic	Alloys, pesticides, wood preservative semiconductors	Toxic, possibly carcinogenic
Boron	Coal, detergents, used to make types of glass and ceramics	Essential trace element, toxic at higher levels, especially to arthropods, used to track sewer line and septic tank failures
Cadmium	Industrial discharge, mining waste, metal plating, plumbing, manufacture of phosphate fertilizers	Toxic to aquatic biota, carcinogenic to humans, kidney is critical target organ
Copper	Alloys, metal plating, electrical wiring, plumbing, automotive brake pads, mining, pesticides, roofs, gutters, flashing and other architectural elements	Essential trace element, toxic to vascular plants and algae at higher levels
Lead	Fuel additive, paint, bullets and shots (ammunition), fishing weights, lead acid batteries	Toxicity (anemia, kidney disease, nervous system), harmful to wildlife
Nickel	Alloys, electroplating, batteries, coins, industrial plumbing	Essential element in some animals, toxic at higher levels
Titanium	Alloys, used as a white pigment for toothpaste, soaps, makeup, paints, paper	Non-toxic, can be used to track sewer line and septic tank failures
Zinc	Galvanized metal surfaces, motor oil and hydraulic fluid, tire dust, industrial waste, wood preservatives, paints, plumbing, batteries, deodorants	Essential element in many metalloenzymes, aids in wound healing, toxic to plants at higher levels

Toxic effects of heavy metals on freshwater organisms are related to water hardness (concentration of  $\text{Ca}^{2+}$  and  $\text{Mg}^{2+}$ ). A higher total hardness level prevents fish from absorbing metals such as lead, arsenic and cadmium into their bloodstream through their gills. Because of this, state water qual-

ity limits for heavy metals are partially derived from total hardness concentrations. The naturally acidic (i.e. low hardness) conditions of most Leon County streams and lakes means that a given amount of heavy metal is more toxic and that water quality limits are correspondingly lower.

Most Leon County soils have a low sorption capacity for metal ions due to high sand content, low pH and low organic material. These characteristics often result in metals being relatively mobile in the environment; meaning that metals can readily and sometimes continually disperse downstream and downwind of their sources.

The above factors are reflected by the three lakes and three streams with trace element levels exceeding Class III water quality standards in 2015 (**Table 2**). The elements that exceeded Class III water quality standards include lead (six stations) and copper (one station). The lead exceedances are thought to be caused by relict anthropogenic sources combined with enhanced metal mobility due to the naturally acidic soil and water conditions commonly found in Leon County. The source of the lone copper exceedance is unknown; however copper is used as an herbicide so there is a possibility that an herbicide was applied near the sampling station.

### **Lake Bradford**

Elevated lead levels in Lakes Bradford, are thought to be due to both relict and potentially current sources. Relict anthropogenic sources of lead in the area include a former shooting range and the former Dale Mabry airfield, while possible current sources include the Tallahassee Regional Airport (aviation fuel). The acidic nature of these lakes causes increased lead levels due to the enhanced solubility of lead under low pH conditions. Because acidic systems like the Bradford Chain of Lakes

are more sensitive to metals contamination, exceedance levels tend to be lower and oftentimes more frequent than a similar metal level in a more alkaline system.

### **Lafayette Creek**

The Lafayette Creek site located at 27 West (Apalachee Pkwy) lead levels exceeded Class III water quality criteria during the 4th quarter of 2015. Prior to sampling, the area received 2.83 inches of rain (11/2/15) that possibly allowed lead contaminated runoff to enter the creek.

### **Polk Creek**

Polk Creek lead levels exceeded Class III water quality criteria during the 2<sup>nd</sup> quarter. Due to the natural soil characteristics of these watersheds, lead from relict anthropogenic sources can migrate relatively easily through the soil, leaching into the surface waters. These surface waters are more susceptible to even low levels of lead due to lead's bioavailability at the stream's normally low pH levels.

### **Lake Iamonia**

Copper levels exceeded Class III water quality criteria during the 4<sup>th</sup> quarter at station IA6 (located approximately 0.43 miles west of the landing at the end of Iamonia Landing Rd.). The source(s) of copper are unknown at this time.

## Lake Munson and Munson Slough

Both Munson Slough and Lake Munson exceeded Class III water quality criteria for

lead in 2015. Relict anthropogenic sources such as leaded gasoline are most likely to be the cause of these exceedances.

**TABLE 2. Trace elements exceeding Class III water quality criteria in Leon County lakes and streams.**

Description	Station Number	Metal of Concern	Results µg/L	Criterion µg/L	Calendar Qtr. Exceeded*
<b>Bradford Chain of Lakes</b>					
Lake Bradford	B0B	Lead	1.3	0.54	4
<b>Lake Iamonia</b>					
Lake Iamonia Station 6	IA6	Copper	3.4	2.85	4
<b>Lafayette Creek</b>					
Lafayette Creek at 27 West	65	Lead	1.3	1.0	4
<b>Lake Munson</b>					
Lake Munson 2	LMU7	Lead	1.1	1.01	4
<b>Munson Slough</b>					
Munson Slough below dam	MS2	Lead	1.2	0.98	4
Munson Slough at Oak Ridge Road	MS5	Lead	1.0	0.99	1
<b>Polk Creek</b>					
Polk Creek at 20	38	Lead	1.0	0.54	2

\*1-1<sup>st</sup> quarter, 2-2<sup>nd</sup> quarter, 3-3<sup>rd</sup> quarter, 4-4<sup>th</sup> quarter