

<b>Second Harvest Capital Improvements</b>	<b>Estimated Costs for Entrepot Blvd.</b>
Roll up door replacement and repairs	\$10,000
Freezer and cooler doors replacement and repairs	5,000
Exclusion exterior repairs	2,000
Refrigeration replacement and repairs	80,000
A/C replacement and repairs	5,000
Plumbing replacement and repairs	2,000
Phone and data system installation	1,000
Lighting and electrical replacement and upgrades	4,000
Interior paint and repair	3,000
Alarm system installation/activation	1,000
Pest Control set up	1,500
Pressure wash and sanitize interior/coolers	7,000