























SAFETY
2011

Employees Must
Wash Hands Before
Returning To Work






SAFETY
FIRST
Employees Must
Wash Hands Before
Returning To Work





SAFETY
2010

Employees Must
Wash Hands Before
Returning To Work












1800-2

DO NOT
BLOCK
TRAFFIC









MANUFACTURERS DATA PLATE

Date of manuf.: 1-17-97 Flood Live Load: 50 Roof Live Load: 20
 Occupancy: Business Seismic Zone: A Wind Zone: 110
 Fire Rating of Ext. Walls: 0 Const. Class: V

EQUIPMENT	MANUFACTURER	MODEL NO.
Heating	<u>Bard</u>	<u>10KW</u>
Air Cond.	<u>Bard</u>	<u>WA361</u>
Cooking		
Refrig.		
Water Heater		
Washer		
Dryer		
Dishwasher		
Garb. Disp.		
Drink Fount.		
Other		

Approval Agency: HWC, Inc.
 Clearwater, Florida 34616
 Serial No. _____
 Manufacturer: Georgia Structures
 Addr: Hwy. 37 West
 Adel, Georgia 31620
 Serial No. GSP970337A-D
 Special Instruction, Conditions
 Limitations, Etc.: _____

This unit constructed in compliance with: 1994 SBC
1994 NFPA 101, 1993 NEC
1994 SMC, 1994 SPL
ADA, ANSI A17.1

Elec. Panel Data 100 AMP 60 HZ | 4120/240V
 Plan No. 2002-183 Model 48x60
 Insignia No.: FL-1004 Thermal Transmitt (U)
GA Export 0003802 Walls R-11
 RF/Cell: R-19
 Floor: R-11

TURN OFF POWER SUPPLYING THIS EQUIPMENT BEFORE WORKING INSIDE.

30-17431

CAUSE SEVERE INJURY OR DEATH.

GEORGIA DEPT. OF COMMUNITY AFFAIRS

No. EX 0003802

THIS UNIT MAY BE ONLY FROM GEORGIA